

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

5/15




FIG. 6

50

GUN STRING 7:15a OK

GUNSTRINGID:

1	<input type="text"/>	8	<input type="text"/>	15	<input type="text"/>
2	<input type="text"/>	9	<input type="text"/>	16	<input type="text"/>
3	<input type="text"/>	10	<input type="text"/>	17	<input type="text"/>
4	<input type="text"/>	11	<input type="text"/>	18	<input type="text"/>
5	<input type="text"/>	12	<input type="text"/>	19	<input type="text"/>
6	<input type="text"/>	13	<input type="text"/>	20	<input type="text"/>
7	<input type="text"/>	14	<input type="text"/>	CONT.	<input type="text"/>

TEST SAVE HELP

408

FIG. 8

50

FIELD TESTER 7:14a OK

ADDRESSABLE SWITCH
FIELD TESTER

WARNING: DETONATORS MUST NOT BE
ATTACHED TO ANY GUN TO PERFORM

NEW
LOAD
DELETE

GUNSTEST HELP

56

406

402

404

400

FIG. 7




FIG. 9




FIG. 10




FIG. 11




FIG. 12

50

TEST (VIEW)

7:39a OK

430

10/17/01

GUNSTRINGID: H1234

OPERATOR: GARY

LOCATION: ROSHARON

NOTE: PDA REVIEW

1 1201

8 1208

15 120F

2 1202

9 1209

16 1210

3 1203

10 120A

17 1211

4 1204

11 120B

18 1212

5 1205

12 120C

19 1213

6 1206

13 120D

20 1214

7 1207

14 120E

CONT.

FIG. 14

50

TESTING COMPLETE 7:22a OK

418

PLEASE ENTER THE FOLLOWING TEST INFORMATION. CLICK ON OK WHEN DONE

420

STARTING GUN NUMBER: 422

424

OPERATOR:

426

LOCATION:

428

NOTE:

123 1 2 3 4 5 6 7 8 9 0 - = +

TAB q w e r t y u i o p l j

CAP a s d f g h j k l ; ' |

SHIFT z x c v b n m , . /

CTL ALT ? %

FIG. 13



11/15




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22